



## **HARTCROWSER**

TORTHERN WOODLANDS

Hart Crowser, Inc. 1910 Fairview Avenue East Seattle, Washington 98102 FAX 206.328.5581 206.324.9530

Earth and Environmental Technologies

### **MEMORANDUM**

DATE: De

December 2, 1993

TO:

Norm Linton; Potlatch Corporation

Gary Parish; Popham, Haik

FROM:

**David Winter** 

RE:

Proposed Draft Replacement for Free Phase Recovery Completion Section

in the Draft Consent Order and Remediation Plan, Avery Landing

J-2294-04

After considerable thought and in-house discussion we have concluded that we probably will have no success proposing an acceptance criteria completely different than the 0.1 inch of free product currently in the draft. This is because we do not have a strong technically-based argument to support our belief that such a cleanup level is neither practically achievable nor necessary for surface water protection. In most free product recovery systems, the practical life or measure of success of the system is determined either on the basis of residual product level (usually measured in wells, and dependent on the well locations) or on the amount of recovered product (usually established based on observed or historical product recovery rates).

Based on these thoughts, we propose keeping the 0.1 inch criteria in place, but offering an option to consider alternatives if the monitoring data we collect in the first year or two of operation suggest that the 0.1 criteria cannot be practically met. For example, at the end of paragraph 7.E., on page 3 of the Consent Order, and after the sentence ending "... and the recovery trench." at the bottom of page 4 of 6 on the Remediation Plan, insert the following sentences:

Potlatch Corporation December 2, 1993

J-2296-04 Page 2

"After collecting at least two years of recovery and monitoring data, Potlatch and CMC may, as part of the annual report, propose an alternative recovery system shutdown criterion. Such an alternative would be based on the probable decreasing product recovery rates and asymptotically decreasing rate of change in monitoring well free product thicknesses over time. A revised criterion considering recovery rate may be appropriate. If the collected data suggest that the free product recovery system in place has attained or nearly attained an asymptotic limiting recovery rate or product thickness or both, the parties to this agreement could agree to the minimum one year system shutdown, even if the free product thickness in the wells and trench exceeds 0.1 inch."

One other note: I have found in our files records of a product sample analysis from 1989 that included test results for arsenic, cadmium, chromium, and lead, plus flash point and total halogens, the information required under Subpart E - Used Oil Burned for Energy Recovery. The test results (summary attached) indicate that the product does not exceed any of the allowable levels of the constituents and properties in the specification table. Our field representative, Chris Holloway, is obtaining additional samples of the product so that we can rerun the analyses, if you wish.

I look forward to discussing these items with you.

DRFTREPL.MEM

#### Attachment:

A - Laboratory Report Summary Spectra Laboratories, Inc.

ATTACHMENT A LABORATORY REPORT SUMMARY SPECTRA LABORATORIES, INC.

## Laboratories, Inc.

5013 Pacific Hwy. E. #12 • Tacoma, WA 98424 • (206) 922-5120

(As), ppm

October 17, 1989

Analytical Resources Inc. 333 Ninth Avenue North Seattle, WA 98109-5187

Customer #81570

Arsenic

Sample ID: MW-4/5-1 3747-C

Desc: Oil

Spectra #27474

RŨSH

<1

Attn: Dave Mitchell

Cadmium (Cd), ppm <1 Chromium (Cr), ppm 1 Lead (Pb), ppm 5

SPECTRA LABORATORIES, INC.

Steven G. Hibbs, Chemist

# SPECTRA Laboratories, Inc.

5013 Pacific Hwy. E. #12 • Tacoma, WA 98424 • (206) 922-5120

October 5, 1989

Analytical Resources Inc. 333 Ninth Ave North Seattle, WA 98109-5187 Customer #81570

Sample ID: MW 4/S-1 ARI #3747-C Spectra #26941

Attn: Catherine Greer

Total halogens, ppm Flash Point, PMCC °F

<1 >210

EP Toxicity Metals, mg/l

Lead	(Pb)	<0.01
Chromium	(Cr)	<0.002
Silver	(Ag)	<0.004
Barium	(Ba)	0.005
Cadmium	(Cd)	<0.005
Arsenic	(As)	<0.08
Mercury	(Hg)	<0.02
Selenium	(Se)	<0.1

SPECTRA LABORATORIES, INC.

Steven G. Hibbs, Chemist